

Table 1 Fibers in Air Levels and Sample locations Commerce Building, 1401 Constitution Avenue NW Washington, DC September 9, 2002

Sample ID	Location	Fibers/cc
COM -1	1 st floor by room 1848	< 0.01
COM -2	1 st floor in room 1524	< 0.01
COM -3	1 st floor by room 1508	< 0.01
COM -4	1 st floor Main Lobby	< 0.01
COM -5	1 st floor in room 1317	< 0.01
COM -6	2 nd floor by room 2308	< 0.01
COM -7	2 nd floor in room 2845	< 0.01
COM -8	2 nd floor in the Auditorium	< 0.01
COM -9	2 nd floor by room 2041	< 0.01
COM -10	3 rd floor by stairwell #2	< 0.01
COM -11	3 rd floor by room 3021	< 0.01
COM -12	3 rd floor by elevator, Corridor 6	< 0.01
COM -13	3 rd floor by elevator, Corridor 5	< 0.01
COM -14	3 rd floor in room 3849	< 0.01
COM -15	3 rd floor by room 3330S	>0.01
COM -16	3 rd floor by room 3312	>0.01
COM -17	3 rd floor by room 3409	< 0.01
COM -18	3 rd floor in Women's Restroom, Corridor 7	>0.01
COM -19	3 rd floor Corridor 2	>0.01
COM -20	3 rd floor Corridor 1	< 0.01



Table 2
Fibers in Air Levels and Sample locations
Commerce Building, 1401 Constitution Avenue NW
Washington, DC
September 10, 2002

Sample ID	Location	Fibers/cc
COM -1	4 th floor in the Office of Technology Administration	< 0.01
COM -2	4 th floor by elevator, Corridor 0	>0.01
COM -3	4 th floor by room 4031	< 0.01
COM -4	4 th floor by elevator, Corridor 4	< 0.01
COM -5	4 th floor in room 4713	>0.01
COM -6	4 th floor in room 4898	>0.01
COM -7	4 th floor Corridor 5	< 0.01
COM -8	4 th floor by elevator, Corridor 3	< 0.01
COM -9	4 th floor by room 4304	< 0.01
COM -10	4 th floor by room 4830	< 0.01
COM -11	4 th floor in room 4728	< 0.01
COM -12	4 th floor in room 4703	< 0.01
COM -13	4 th floor Corridor 3	< 0.01
COM -14	5 th floor in room 5708	< 0.01
COM -15	5 th floor by room 5730	< 0.01
COM -16	5 th floor in room 5897	< 0.01
COM -17	5 th floor by room 5626	< 0.01
COM -18	5 th floor by elevator, Corridor 6	< 0.01
COM -19	Field Blank	N/A
COM -20	Field Blank	N/A

N/A Denotes Not Applicable



Table 3 Fibers in Air Levels and Sample locations Commerce Building, 1401 Constitution Avenue NW Washington, DC September 11, 2002

Sample ID	Location	Fibers/cc
COM -1	5 th floor by elevator, Corridor 5	< 0.01
COM -2	5 th floor by room 5882	< 0.01
COM -3	5 th floor in Women's Restroom, Corridor 4	< 0.01
COM -4	5 th floor by room 5045	< 0.01
COM -5	5 th floor by room 5310	< 0.01
COM -6	5 th floor in room 5323	< 0.01
COM -7	5 th floor in room 5128-NOAA	< 0.01
COM -8	5 th floor by room 5102	< 0.01
COM -9	5 th floor Corridor 2	< 0.01
COM -10	6 th floor in room 6102	< 0.01
COM -11	6 th floor by room 6217	< 0.01
COM -12	6 th floor in room 6015	< 0.01
COM -13	6 th floor by room 6029B	< 0.01
COM -14	6 th floor in room 6827	< 0.01
COM -15	6 th floor Corridor 3	< 0.01
COM -16	6 th floor in Women's Restroom, Corridor 2	< 0.01
COM -17	6 th floor Corridor 1	< 0.01
COM -18	6 th floor Corridor 7	< 0.01
COM -19	6 th floor in Copy Center, Corridor 8	< 0.01
COM -20	6 th floor Corridor 4	< 0.01



Table 4 Fibers in Air Levels and Sample locations Commerce Building, 1401 Constitution Avenue NW Washington, DC September 12, 2002

Sample ID	Location	Fibers/cc
COM -1	5 th floor in Secretary's Reception	< 0.01
COM -2	6 th floor in room 6826	< 0.01
COM -3	6 th floor by room 6057	< 0.01
COM -4	6 th floor in room 6874	< 0.01
COM -5	6 th floor by room 6631	< 0.01
COM -6	6 th floor in room 6703	< 0.01
COM -7	7 th floor Corridor 6	< 0.01
COM -8	7 th floor by room 7721	< 0.01
COM -9	7 th floor by elevator, Corridor 5	< 0.01
COM -10	7 th floor in the Library	< 0.01
COM -11	7 th floor by room 7029B	< 0.01
COM -12	7 th floor by room 7824	< 0.01
COM -13	7 th floor in room 7227	< 0.01
COM -14	7 th floor Corridor 2	< 0.01
COM -15	7 th floor by room 7118	< 0.01
COM -16	7 th floor by room 7804	< 0.01
COM -17	7 th floor by elevator, Corridor 3	< 0.01
COM -18	7 th floor Corridor 1	< 0.01
COM -19	7 th floor Corridor 0	< 0.01
COM -20	7 th floor in Women's Restroom, Corridor 4	< 0.01



Table 5 Fibers in Air Levels and Sample locations Commerce Building, 1401 Constitution Avenue NW Washington, DC September 13, 2002

Sample ID	Location	Fibers/cc
COM -1	Sub Basement, Corridor 0	< 0.01
COM -2	Sub Basement, Corridor 6	< 0.01
COM -3	Sub Basement, Corridor 8	< 0.01
COM -4	Sub Basement in room SB894	< 0.01
COM -5	Basement Mezzanine in room BM07	< 0.01
COM -6	Basement Mezzanine in room BM27	< 0.01
COM -7	Basement Mezzanine by room BM15	< 0.01
COM -8	1 st floor in room 1617	< 0.01
COM -9	1 st floor by room 1603	< 0.01
COM -10	Attic, by room 8014	< 0.01
COM -11	Attic, by room of Elevator Group #4	< 0.01
COM -12	Attic, by the ladder to roof	< 0.01
COM -13	Attic, Corridor 0	< 0.01
COM -14	Attic, Corridor 3	< 0.01
COM -15	Attic, in room 8062	< 0.01
COM -16	Attic, Corridor 8	< 0.01
COM -17	Attic, Corridor 4	< 0.01
COM -18	Attic, Corridor 2	< 0.01
COM -19	Attic, Corridor 0	< 0.01
COM -20	Attic, Corridor 8	< 0.01



Table 6 Fibers in Air Levels and Sample locations Commerce Building, 1401 Constitution Avenue NW Washington, DC September 16, 2002

Sample ID	Location	Fibers/cc
COM -1	Basement, in room B805	< 0.01
COM -2	Basement, in room B826	< 0.01
COM -3	Basement, by room B525	< 0.01
COM -4	Basement, in room B626	< 0.01
COM -5	Basement, in room B618	< 0.01
COM -6	Basement, Corridor 2	< 0.01
COM -7	Basement, Corridor 3	< 0.01
COM -8	Basement, by the Market Place	< 0.01
COM -9	Basement, Corridor 8	< 0.01
COM -10	Basement, by the Credit Union	< 0.01
COM -11	1 st floor by room 1227	< 0.01
COM -12	1 st floor in room 1103	< 0.01
COM -13	1 st floor by room 1112	< 0.01
COM -14	1 st floor, by elevator, Corridor 0	< 0.01
COM -15	1 st floor by elevator, Corridor 8	< 0.01
COM -16	2 nd floor by room 2213	< 0.01
COM -17	2 nd floor by room 2015A	< 0.01
COM -18	2 nd floor in Women's Restroom, Corridor 1	< 0.01
COM -19	2 nd floor in room 2231	< 0.01
COM -20	2 nd floor by elevator, Corridor 8	< 0.01